



Project Area



Surrounding Area



Comment Legend

- Idea
- Info
- Negative
- Positive
- Cattle Poaching
- Paths
- Dog walking, cycling, walking

Consultation Comments

1	Bank erosion as a result of flow	24	Rushes, overgrowing	49	Some properties local authority, some privately owned.	73	Willow + reeds maintained	98	Very fast and narrow
2	Reed over growth	25	Bird watchers (some regularly)	50	Who is responsible for bank?	74	Berm	99	Building gardens on the other side
3	Scrub overgrowth	26	People like this	51	Floods in summer, used to only flood in winter	75	Brush berms required to create pinch points	100	Fishing
4	Weedy possibly from farmers chemicals	27	Part submerged barbed wire fence/wildlife hazard	52	Soil monitoring points along here	76	Short piling	101	Jubilee River bird wildlife in abundance. A huge asset to "country" life
5	Bank erosion, dead spot	28	Local community water quality monitoring	53	Is this capped bank/hill contaminated under?	77	Stream narrowing	102	160 cubic m/s, 180 cubic m/s (2013 - 14)
6	Clumps of weed down river.	29	Undercutting	54	Brook is capped off with steel piles restricting Cole Norton flow	78	Cut back old trees	103	Frequent damming due to branches being thrown in river
7	Water voles reintroduction	30	Very shallow point	55	Designated public path	79	Riverfly reintroduction	104	Weed build up on Eton College
8	Over wide	31	Concrete garages. Can these be covered?	56	Bank eroding	80	Fencing to prevent cattle encroachment	105	Good wildlife in practise section of Ruondmoor Lake. Cormorants, etc.
9	Dissolved oxygen meter	32	Who owns this (Radian)	57	Garden refuse	81	Introduce bankside vegetation: purple loosestrife, flac, common pond sedge	106	Not connected
10	Water quality	33	Kingfishers	58	Garden refuse	82	Proper cattle drink	107	Church of St. Mary Magdaline. Friends of Friendless
11	TW quality improvement, has reduced food resource in Roundmoor Ditch	34	Tree, pulling out bank	59	Erosion of bank	83	Bank erosion at bottom of garden	108	Scout hut
12	Bird watching	35	Deepest part	60	Danger for children	84	More events along Jubilee leading to more litter	109	Archaeological evidence of fish pens
13	Flooding partly caused by cattle	36	Electrical feed cable around here	61	Running events - refuse	85	Pair of kingfishers	110	Large fish here can only have come from downstream
14	Lots of daice/roach 2015	37	Dog bins	62	Pair of kingfishers nesting here	86	Iron bridge, Thames Confluence, Thames level drops and empties the lower part of the river	111	Stagnant, no flow
15	Destruction of bird habitat (resting) by ebb and flow of brook	38	Used to fish as a kid	63	Waders, warblers	87	Brook is stagnant, full of rubbish	112	Flows east
16	Kingfishers	39	Used to be big fish here	64	Water rising and falling 8in every day	88	Very stagnant, no flow	113	Flow prevented
17	Barbel/chub spawning area April-June	40	Where are the fishermen?	65	Mink coming up from the Thames disappeared when the river dropped	89	Simply Walks - walking group. Jubilee River, Dorney Common, Thames	114	Flow deflectors + gravel replenishment
18	spawn increase -> 2012 (fish). 2013 -> drop off fish spawn. 2016-2017 -> Low no fish	41	Facebook group "Only in Eton Wick" good place for local comms	66	Ditch has changed since bank repairs. Now still with less oxygenation. Plants (Elodea, Cabomba), more surface plants, etc.	90	Bought house because of view of river and common	115	Fish population increase, now installed deflectors
19	Pools present, form holds. However, cores removed surface, exposing sholls	42	Public footbridge needs attention. Who's responsible?	67	Cress is a backwater. No flow from across the common.	91	Mink invasion, no water voles	116	Copthorne Hotel, Queen Avenue Springs
20	Dead area, no flow!	43	Cattle access into water when low + getting into come gardens. But fencing the common would be detrimental. Totally against this!	68	New plank bridge. Bucks C. C. Palmers to agree bridge.	92	Independent monitoring system for local people to keep in check	117	Information on chalk aquifers
21	Advertise at bus stops	44	Erosion	69	No public right of way -> palmers making right of way. New bridge	93	Jubilee - can some of the flow go into the ditch to improve natural flow?	118	watercress beds (area the p.ts)
22	Fishing stopped completely. Like my bank. Restored naturally	45	Erosion here	70	Main river comorants come up into the Roundmoor	94	Flow	119	Allotments. Water table has dropped after Jubilee built
23	Like the wildlife. Likes not being overlooked + the view	46	Lack of fish now	71	Proper cattle drink(s)	95	Erosion now ok	120	Local paper shop. Good communication channel!
		47	Grass clippings/illegal tipping	72	Remove fence	96	Bird habitat	121	Great walk
		48	Erosion			97	Garden waste thrown over the fence	122	Very silty, used to be dredged, can we create a strategy for managing the s